

# General Environmental Incident Summary

**Incident:** 2069      **Date/Time Notice:** 10/15/2013      1011      **DEM Incident No:**  
**Responsible Party:** Magellan Pipeline Company, LP  
**Date Incident:** 10/14/2013      **Time Incident:** 0900      **Duration:** 5 minutes  
**County:** Cass      **Twp:** 139      **Rng:** 49      **Sec:** 4      **Qtr:** SW SW SW  
**Lat:** 46.88356      **Long:** -96.87230      **Method:** Derived from TRS  
**Location Description:** Magellan Pipeline Company, 902 Main Avenue East, West Fargo, ND

**Submitted By:** Scott Benik

**Affiliation:**

**Address:**

**City:**

**State:**

**Zip:**

**Received By:**

**Contact Person:** Scott Benik  
902 Main Avenue East  
West Fargo, ND 58078

**Distance Nearest Occupied Building:** 500 Feet

**Type of Incident:** Butane Offloading vent pipe

**Description of Released Contaminant:** Butane

**Volume Spilled:** 2.00 gallons

**Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Reported to NRC:** No

**Cause of Incident:**

One-half inch diameter open ball valve on a butane truck-to-tank offloading connection.

**Risk Evaluation:**

None.

**# of Fatalities:** 0

**# of Injuries:** 0

**Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

None.

**Action Taken or Planned:**

Affected soil containerized for disposal.

**Wastes Disposal Location:** To be determined.

**Agencies Involved:**

## ***Updates***

---

***Date:*** 10/15/2013 ***Status:*** Reviewed - No Action Required

***Author:*** Roberts, Kris

***Updated Volume:***

***Notes:***

Small release of a very volatile hydrocarbon. Impacted soil immediately containerized for disposal.  
No follow-up necessary.